

CONSOL Energy Inc  
Form 8-K  
August 02, 2012

**UNITED STATES**  
**SECURITIES AND EXCHANGE COMMISSION**

Washington, D.C. 20549

**FORM 8-K**

**CURRENT REPORT**

**PURSUANT TO SECTION 13 OR 15(d) OF THE**  
**SECURITIES EXCHANGE ACT OF 1934**

**Date of Report (Date of earliest event reported): July 29, 2012**

**CONSOL Energy Inc.**

(Exact name of registrant as specified in its charter)

**Delaware**  
(State or other jurisdiction  
of incorporation)

**001-14901**  
(Commission  
File Number)

**51-0337383**  
(IRS Employer  
Identification No.)

Edgar Filing: CONSOL Energy Inc - Form 8-K

**CNX Center**

**1000 CONSOL Energy Drive**

**Canonsburg, Pennsylvania 15317**

**(Address of principal executive offices)**

**(Zip code)**

**Registrant's telephone number, including area code:**

**(724) 485-4000**

**Not applicable**

**(Former name or former address, if changed since last report)**

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligation of the registrant under any of the following provisions (*see* General Instruction A.2. below):

- ..  Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
- ..  Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
- ..  Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
- ..  Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

**Item 1.04 Mine Safety - Reporting of Shutdowns and Patterns of Violations.**

On July 29, 2012, Consolidation Coal Company, a subsidiary of CONSOL Energy Inc. (the Company ) and the operator of the Company s Robinson Run Mine located in Mannington, West Virginia, received an imminent danger order (the Order ) from the Mine Safety and Health Administration with respect to the Robinson Run Mine under Section 107(a) of the Federal Mine Safety and Health Act of 1977. The Order described an ignition that occurred during cutting operations related to maintenance on the longwall. No injuries resulted from the condition described in the Order and the Order was subsequently abated.

**SIGNATURES**

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

CONSOL ENERGY INC.

By: /s/ Stephen W. Johnson  
Stephen W. Johnson  
Senior Vice President and General Counsel

Dated: August 1, 2012